

Historic American Engineering Record

INDEX  
TO PHOTOGRAPHS

HAER No. WA-131-A

HAER  
WASH  
18-BAISL  
1A-

Pacific Creosoting Plant, Engine Room Building (Retort Room)  
5350 Creosote Place NE  
Bainbridge Island  
Kitsap County  
Washington

John Stameta, photographer

August 1995

HAER No.      Description

- WA-131-A-1 Distant view shows Engine Room Building behind cranes. Retort rings in foreground were once located in Engine Room Building. See photo WA-131-A-2. Building on left is Machine Shop. Boiler Building is in front of stack.
- WA-131-A-2 Oblique view of west corner shows mainly NW side of partially dismantled building. In 1994 circular braces still supported retorts in which wood was processed with creosote.
- WA-131-A-3 Oblique view shows east corner. Pipe loops in roof are part of a condenser apparatus for the retorts. Ruin in foreground was concrete foundation for a water cooling tank.
- Note: The following HAER photocopy is an 8x10" high-contrast copy photograph made from a 1948 drawing in the collection of the regional office of the Environmental Protection Agency, Seattle, WA.
- WA-131-A-4 Engineering drawing of a timber incisor constructed by West Coast Wood Preserving Company, dated 7-2-40.